

## WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3396489-118-2024

MDE OFFICIAL CONTACTED: EVELYN STRAUVAO

DATA CALLED IN BY: MARVIN BAILEY DATE: 09/18/2024 AT 02:00PM

WORK ORDER(S): 3396489 3396476

EST DATE AND TIME SSO BEGAN: 09/18/2024 10:45AM DURATION: 1.42 HRS DATE AND TIME SSO ENDED: 09/18/2024 12:10PM

SOURCE-OVERFLOWING MH MH12024053 WATER BODY AFFECTED-LITTLE FALLS

- CLOSEST STREET ADDRESS: 4905 BRADLEY BLVD 20815 COUNTY/PAGE/GRID: M 5407 E04 TOWN/CITY: CHEVY CHASE
- CAUSE: GREASE AND WIPES EST OVERFLOW VOLUME: 170 GAL UPON ARRIVAL, THE CREW FOUND MANHOLE 053U OVERFLOWING 2GPM, GOING ONTO THE PAVEMENT AND INTO A STORM DRAIN THAT OUTFALLS INTO THE LITTLE FALLS BASIN. THE CREW JETTED FROM MANHOLE 130U TO 053U, A TOTAL OF 77', AND HIT AND RELIEVED A GREASE AND WIPES BLOCKAGE AT 70', TO END THE EVENT.
- IMPACTS UPON PUBLIC HEALTH AND STATE WATERS: WET WEATHER PUBLIC ACCESS PUBLIC USE OBSERVED

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE: THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC-TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: FLUSHED BACK INTO MANHOLE VISIBLE SOLIDS REMOVED

THE CREW WASHED DOWN THE AREA WITH DECHLORINATED WATER AND FLUSHED THE SOLIDS BACK INTO THE MANHOLE.

NOTIFICATIONS MADE: MD DEPARTMENT OF ENVIRONMENT MONTGOMERY CO MUNICIPALITIES

DEP-MONTGOMERY COUNTY