

## WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3432823-118-2025

MDE OFFICIAL CONTACTED: EVEYLYN STAVROU

DATA CALLED IN BY: 4581 DATE: 01/30/2025 AT 11:00AM

WORK ORDER(S): 3432823 3432797

EST DATE AND TIME SSO BEGAN: 01/30/2025 09:20AM DURATION: 2.67 HRS

DATE AND TIME SSO ENDED: 01/30/2025 12:00PM

SOURCE-OVERFLOWING MH MH26003047 WATER BODY AFFECTED-PATUXENT RIVER

CLOSEST STREET ADDRESS: 17721 PRINCE PHILIP D
COUNTY/PAGE/GRID: M 5050 A07 TOWN/CITY: OLNEY PRINCE PHILIP DR 20832

CAUSE: ROOTS EST OVERFLOW VOLUME: 801 GAL UPON ARRIVAL, THE CREW FOUND MANHOLE 047M OVERFLOWING AT 5GPM INTO JAMES CREEK. THE CREW JETTED FROM MANHOLE 046U TO 047M A TOTAL OF

391', AND HIT AND RELIEVED A ROOT BLOCKAGE AT 387', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS: DISCOLORATION

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE: THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC-TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:

FLUSHED BACK INTO MANHOLE T.TMF. VISIBLE SOLIDS REMOVED

THE CREW REMOVED VISIBLE SOLIDS, AND SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE,

NOTIFICATIONS MADE:

MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY

MONTGOMERY CO MUNICIPALITIES

SIGNS POSTED: 16 POST DATE: 01/30/2025