



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3340442-118-2024

MDE OFFICIAL CONTACTED: EVELYN STARVOU

DATA CALLED IN BY: DIARRA K MACKALL DATE: 03/19/2024 AT 01:25PM

WORK ORDER(S): 3340442 3340396

EST DATE AND TIME SSO BEGAN: 03/19/2024 10:40AM DURATION: 2.42 HRS
DATE AND TIME SSO ENDED: 03/19/2024 01:05PM

SOURCE-OVERFLOWING MH MH12024053 WATER BODY AFFECTED-LITTLE FALLS

CLOSEST STREET ADDRESS: 4849 LELAND ST 20815
COUNTY/PAGE/GRID: M 5407 E04 TOWN/CITY: CHEVY CHASE

CAUSE: DEBRIS EST OVERFLOW VOLUME: 726 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 053U OVERFLOWING 5GPM, ENTERING
A STORM DRAIN THAT OUTFALLS IN THE LITTLE FALLS BASIN.
THE CREW JETTED FROM MANHOLE 130U TO 053U A TOTAL OF 77FT, AND HIT
AND RELIEVED A SOFT DEBRIS BLOCKAGE AT 73FT', TO END THE EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER DISCOLORATION
NOTICEABLE ODOR PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
FLUSHED BACK INTO MANHOLE

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT MONTGOMERY CO MUNICIPALITIES
DEP-MONTGOMERY COUNTY

THIS EVENT WAS ORIGINALLY REPORTED AS 4905 BRADLEY BOULEVARD.

SIGNS POSTED: 8 POST DATE: 03/19/2024