



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3348280-118-2024

MDE OFFICIAL CONTACTED: NIKKI MCGUIRE

DATA CALLED IN BY: SHEMIEKA MONIQUE HARDING DATE: 04/18/2024 AT 05:08PM

WORK ORDER(S): 3348280 3348252

EST DATE AND TIME SSO BEGAN: 04/18/2024 03:02PM DURATION: 2.97 HRS
DATE AND TIME SSO ENDED: 04/18/2024 06:00PM

SOURCE-OVERFLOWING MH MH03020084 WATER BODY AFFECTED-BEAVERDAM BRANCH

CLOSEST STREET ADDRESS: 3520 BRIGHTSEAT RD 20785
COUNTY/PAGE/GRID: P 5531 C01 TOWN/CITY: HYATTSVILLE

CAUSE: DAMAGED BY OTHERS EST OVERFLOW VOLUME: 356 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 084N OVERFLOWING AT 2GPM ONTO THE HOMEOWNERS FRONT YARD. THE CREW JETTED FROM MANHOLE 050M TO MANHOLE 051U, AND HIT AND RELIEVED A HEAVY PAPER AND ASPHALT BLOCKAGE AT 230', TO END THE EVENT. THE SOURCE OF THE ASPHALT WAS FROM A RECENT NON-WSSC PAVING PROJECT ON THE STREET.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER NOTICEABLE ODOR
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT PG COUNTY HEALTH DEPT
PG COUNTY MUNICIPALITIES

SIGNS POSTED: 2 POST DATE: 04/18/2024