



# WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3374934-118-2024

MDE OFFICIAL CONTACTED: MS CARLTON

DATA CALLED IN BY: PARIS S JORDAN

DATE: 07/01/2024 AT 02:30PM

WORK ORDER(S): 3374934 3374926

EST DATE AND TIME SSO BEGAN: 07/01/2024 01:03PM DURATION: 2.45 HRS  
DATE AND TIME SSO ENDED: 07/01/2024 03:30PM

SOURCE-OVERFLOWING MH SS05167061 WATER BODY AFFECTED-ROCK CREEK

CLOSEST STREET ADDRESS: 17612 MILL CREEK DR 20855  
COUNTY/PAGE/GRID: M 5048 E07 TOWN/CITY: ROCKVILLE

CAUSE: ROOTS EST OVERFLOW VOLUME: 147 GAL  
UPON ARRIVAL, THE CREW FOUND MANHOLE 061M OVERFLOWING 1 GALLON PER  
MINUTE ONTO THE GRASS AROUND THE MANHOLE. THE CREW JETTED FROM  
MANHOLE 062U TO 033U, AND HIT AND RELIEVED ROOTS AT 300' TO END THE  
EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:  
DRY WEATHER DISCOLORATION  
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:  
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE  
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED  
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE  
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:  
LIME

LIME WAS SPREAD ON IMPACTED GRASS AREAS

NOTIFICATIONS MADE:  
MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY  
MONTGOMERY CO MUNICIPALITIES

ORIGINALLY REPORTED AS 17616 MILL CREEK DRIVE

SIGNS POSTED: 3 POST DATE: 07/01/2024