



WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3413039-118-2024

MDE OFFICIAL CONTACTED: KELLY KITCHENS REF165056

DATA CALLED IN BY: DIARRA K MACKALL DATE: 11/17/2024 AT 04:32PM

WORK ORDER(S): 3413039 3413034

EST DATE AND TIME SSO BEGAN: 11/17/2024 02:45PM DURATION: 3.08 HRS
DATE AND TIME SSO ENDED: 11/17/2024 05:50PM

SOURCE-OVERFLOWING MH MH10019092 WATER BODY AFFECTED-NORTHWEST BRANCH

CLOSEST STREET ADDRESS: 5001 37TH AVE 20782
COUNTY/PAGE/GRID: P 5409 G08 TOWN/CITY: BRENTWOOD

CAUSE: GREASE EST OVERFLOW VOLUME: 924 GAL
UPON ARRIVAL, THE CREW FOUND MANHOLE 092M OVERFLOWING AT 5GPM ONTO
THE GRASSY AREA AROUND THE MANHOLE. THE CREW JETTED FROM MANHOLE
092M TO 007T A TOTAL OF 240', AND RELIEVED GREASE AT 194', TO END THE
EVENT.

IMPACTS UPON PUBLIC HEALTH AND STATE WATERS:
DRY WEATHER NOTICEABLE ODOR
PUBLIC ACCESS

STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE:
THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE
ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUCTED
TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE
THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT:
LIME

THE CREW SPREAD LIME AND PLACED TWO BALES OF HAY IN THE GRASSY AREA
AROUND THE MANHOLE.

NOTIFICATIONS MADE:
MD DEPARTMENT OF ENVIRONMENT PG COUNTY HEALTH DEPT
PG COUNTY MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 5001 R/W 37TH AVENUE.

SIGNS POSTED: 5 POST DATE: 11/17/2024