

WASHINGTON SUBURBAN SANITARY COMMISSION SANITARY SEWER OVERFLOW WRITTEN REPORT

3433820-118-2025

MDE OFFICIAL CONTACTED: CHRIS SHAFFNER

DATA CALLED IN BY: MARVIN BAILEY DATE: 02/03/2025 AT 09:30PM

WORK ORDER(S): 3433820 3433780

EST DATE AND TIME SSO BEGAN: 02/03/2025 04:51PM DURATION: 2.65 HRS DATE AND TIME SSO ENDED: 02/03/2025 07:30PM

SOURCE-OVERFLOWING MH MH07091009 WATER BODY AFFECTED-CABIN JOHN

CLOSEST STREET ADDRESS: 6009 NEILWOOD DR 20852-3703 COUNTY/PAGE/GRID: M 5285 A03 TOWN/CITY: ROCKVILLE

- CAUSE: ROOTS AND WIPES EST OVERFLOW VOLUME: 159 GAL UPON ARRIVAL, THE CREW FOUND MANHOLE 009M OVERFLOWING AT 1GPM, ONTO THE GRASSY AREA AROUND THE MANHOLE, AND INTO A TRIBUTARY OF CABIN JOHN CREEK. THE CREW JETTED FROM MANHOLE 008M TO 009M, A TOTAL OF 274', AND HIT AND RELIEVED A HEAVY ROOTS AND WIPES BLOCKAE AT 175', TO END THE EVENT.
- IMPACTS UPON PUBLIC HEALTH AND STATE WATERS: DRY WEATHER DISCOLORATION NOTICEABLE ODOR PUBLIC ACCESS
- STEPS TAKEN OR PLANNED TO REDUCE, ELIMINATE AND PREVENT RECURRENCE: THE PROBLEM WITH THIS SEWER LINE HAS BEEN REFERRED TO LINE BLOCKAGE ANALYSIS (LBA) FOR REVIEW. A FOLLOW-UP INVESTIGATION WILL BE CONDUC-TED TO DETERMINE WHAT MEASURES SHOULD BE TAKEN TO REDUCE OR ELIMINATE THE CHANCE OF THIS LINE OVERFLOWING AGAIN.

MEASURES INITIATED/TAKEN TO MINIMIZE IMPACT: LIME

THE CREW SPREAD LIME IN THE GRASSY AREA AROUND THE MANHOLE.

NOTIFICATIONS MADE: MD DEPARTMENT OF ENVIRONMENT DEP-MONTGOMERY COUNTY MONTGOMERY CO MUNICIPALITIES

THIS EVENT WAS ORIGINALLY REPORTED AS 6006 EXECUTIVE BOULEVARD.

SIGNS POSTED: 5 POST DATE: 02/04/2025